



eksckby u-a 9826033338 9893311118

yk;lsal ua-

18/15438/UJN/85H

PERFORMANCE REPORT

MODEL INSTALLAED - W4 ON 12/11/2023

Installed in recircula on mode in pool of 80 KL tank.

We are thankful to WTS, who has given this solution to resolve our recurring problems in operation. Our ground water is too hard and leads to building up the scales in pipeline and compressor heads, also we were facing the algae forma on issue.

A er installation of WTS – W4, we stopped chemical dosing and operations are hassle free. Till date scaling in the pipelines is not observed and algae forma on issue have been resolved by 60%.

We appreciate this technology and will communicate this idea and help you in promotion; in our domain.

Regards

PRABHATASHIRWAL (Owner)
Shri Radhe Erichta Cold Stonge

82, <kcyk jsgokjh] vkxj jksM+] mTtSu e-Ikz- 456550